

TRANSCOAT 570

Degreaser

Product Description A quick-working cleaner for removing heavy deposits of oil, grease, alkali, or tar from metal, concrete or previously painted surfaces.

Recommended Use A heavy-bodied liquid that can be applied by brush as a thick coat which dissolves and picks up grease or tar. When the oily material has been loosened, it can be removed by hosing with clean water.

Characteristics

- Cleans better than solvent type cleaners.
- It lifts heavy oil deposits off of the surface so that the residue can be washed away with water without spreading the oil or leaving any residue. When dry, the surface is ready for either abrasive blasting, or for application of a protective coating.
- Relatively nonhazardous to use, it contains no caustic or corrosive chemicals and no toxic chlorinated materials.

Physical Data	Flash Point	160°F Tag Open Cup, minimizing fire hazards during use
	Shelf Life	At least 12 months
	Pack Size	20 litres

Application Data	Application Methods	
	Brush	Recommended

Instructions

- Stir thoroughly before using.
- Brush Transcoat 570 on surface to be cleaned, at a coverage of 3.5 - 5 sq.m/ltr.
- Allow to remain on the surface from 5 - 20 minutes, then scrub off with a stiff brush or broom. The longer the Transcoat 570 can be allowed to work before scrubbing, the more effective it is in loosening heavy deposits. However, it should NOT be allowed to dry.
- Hose off with water under high pressure. On rough or pitted surfaces, it may be necessary to scrub with a stiff brush while washing. Hot water or low-pressure steam greatly facilitates removal.
- If any deposits of tar or heavy oil remain, repeat the application of Transcoat 570 and scrub with a stiff brush. Wash again with water as described above.

Safety Precaution This product is combustible. Keep away from heat and open flame. Keep container closed. Use with adequate ventilation. Avoid prolonged breathing of vapour. Avoid prolonged and repeated contact with skin. In tanks and other confined areas, observe the following precautions to prevent hazards of fire or explosion or damage to the health:

- Circulate adequate fresh air continuously during application and drying.
- Use fresh air masks and explosion-proof equipment.
- Prohibit all flames, sparks, welding and smoking.

TRANSCOAT 570

Degreaser

See Transcoat application instructions included with shipment for equipment and methods recommended for safe application procedure.

Disclaimer

The information in this product data sheet is given to the best of our knowledge based on laboratory testing and practical experience. If the product is used under condition beyond our control, we cannot guarantee anything but the quality of the products it self. The information in this product data sheet is liable for modification from time to time in the light of experience and our policy of continuous product development, and without further notice.
